

## Certificate of compliance of European Directive ROHS 2011/65/UE

I, the undersigned, duly authorized to sign for

FLEXELEC  
10, rue des Frères Lumière  
Z.A. du Bois Rond  
69 720 Saint Bonnet de Mure  
France

Hereby certify that the components:

FST, FSV, FSX, FSG, FSHTP electric heat-tracing cables

Are compliant with the requirements imposed by the European Directive 2011/65/UE of the European Parliament and of the Council of 8 June 2011 on the restriction of the use of certain hazardous substances in electrical and electronic equipment and specifically that the component does contain:

- Lead ( Pb ; max 0.1 weight % )
- Mercury ( Hg ; max 0.1 weight % )
- Hexavalent chromium ( Cr VI ; max 0.1 weight % )
- Polybrominated biphenyls ( PBB; max 0.1 weight % )
- Polybrominated dophenyl ethers ( PBDE; max 0.1 weight % )
- Cadmium (Cd; max 0.01 weight % )

Saint Bonnet de Mure, 16/09/2011

**Pierre FERRAND**  
Technical manager



10 rue des Frères Lumière – Z.A. du Bois Rond  
69720 SAINT BONNET DE MURE – France  
Tél. + 33 (0)4 72 48 30 90 – Fax + 33 (0)4 78 40 82 81

## Certificate of compliance of European Directive ROHS 2011/65/UE

I, the undersigned, duly authorized to sign for

FLEXELEC  
10, rue des Frères Lumière  
Z.A. du Bois Rond  
69 720 Saint Bonnet de Mure  
France

Hereby certify that the components:

FST/T (or TP, TF), FSV/T (or TF), FSX/TF, FSX/T, FSG/T (or TP, TF) electric heat-tracing cables 

Are compliant with the requirements imposed by the European Directive 2011/65/UE of the European Parliament and of the Council of 8 June 2011 on the restriction of the use of certain hazardous substances in electrical and electronic equipment and specifically that the component does contain:

- Lead ( Pb ; max 0.1 weight % )
- Mercury ( Hg ; max 0.1 weight % )
- Hexavalent chromium ( Cr VI ; max 0.1 weight % )
- Polybrominated biphenyls ( PBB; max 0.1 weight % )
- Polybrominated dophenyl ethers ( PBDE; max 0.1 weight % )
- Cadmium (Cd; max 0.01 weight % )

Saint Bonnet de Mure, 16/09/2011

**Pierre FERRAND**  
Technical manager

